

Northeast Reliability Interconnect

Bangor Hydro-Electric Company



U.S.G.S. data: Monroe Lake Quadrangle, 1990



Balloon on the left.



Balloon on the right.

Existing Conditions 10A
Existing view from the southerly end of First Machias Lake near an informal campsite. Two reference weather balloons are visible approximately 1 mile to the north. Photographs by TJD&A, October 1, 2004.



Northeast Reliability Interconnect

Bangor Hydro-Electric Company



U.S.G.S. data: Monroe Lake Quadrangle, 1990

Photosimulation 10B

Photosimulation of the proposed project from the southerly end of First Machias Lake near an informal campsite. The upper portion of one structure will be visible. Photograph by TJD&A, October 1, 2004.